GENTEX CORPORATION

August 31, 2019

Effective October 31, 2019, Gentex will discontinue the 8000 Series system smoke detectors from our product line.   Due to a declining market need for this type of smoke detector, a replacement will not be offered.

The model numbers listed below are affected by this notice:

8100 Series	
Gentex Part Number	Gentex Model Number
908-1233-002	8100
908-1234-002	8100T
908-1235-002	8100H
908-1239-002	8100Y

8240 Series	
Gentex Part Number	Gentex Model Number
908-1201-002	8240
908-1203-002	8240T
908-1204-002	8240H
908-1207-002	8240Y

8103 Series	
Gentex Part Number	Gentex Model Number
908-1243-002	8103P
908-1244-002	8103PT
908-1245-002	8103PH
908-1246-002	8103PY
908-1247-002	8103PTY
908-1248-002	8103PHY

8243 Series	
Gentex Part Number	Gentex Model Number
908-1211-002	8243P
908-1212-002	8243PT
908-1213-002	8243PH
908-1214-002	8243PY
908-1215-002	8243PTY
908-1216-002	8243PHY

Orders are subject to availability.

Thank you for your continued support.